INSPECTION REPORTWorker and Employer Services Division



6951 Westminster Highway, Richmond, BC Mailing Address: PO Box 5350, Vancouver BC, V6B 5L5 Telephone 604 276-3100 Toll Free 1-888-621-7233 Fax 604 276-3247

The Workers Compensation Act requires that the employer must post a copy of this report in a conspicuous place at or near the workplace inspected for at least seven days, or until compliance has been achieved, whichever is the longer period. A copy of this report must also be given to the joint committee or worker health and safety representative, as applicable.

Inspection Report #201811321045A			
Employer Name	Jobsite Inspected	Scope of Inspection	
CITY OF PENTICTON	459 Waterloo Avenue Penticton BC V2A 7N1	Waste Water Treatment Plant - AMC	

Date of Initiating Inspection	Date of This Inspection	Delivery Date of This Report	Delivery Method
Aug 28, 2018	Aug 28, 2018	Sep 18, 2018	Email

THERE ARE ZERO (0) ORDERS OR OTHER ITEMS OUTSTANDING

ACTION MAY STILL BE NECESSARY TO ENSURE COMPLIANCE PLEASE READ FULL REPORT



6951 Westminster Highway, Richmond, BC Mailing Address: PO Box 5350, Vancouver BC, V6B 5L5 Telephone 604 276-3100 Toll Free 1-888-621-7233 Fax 604 276-3247

INSPECTION NOTES

The City of Penticton operates Waste Water Treatment facility located at 459 Waterloo Avenue. This plant treats waste water for the City of Penticton. The facility has developed "Alternate Measures" for entry into lower screw pump sump area (moderate confined space based on hazard assessment). They are planning to conduct a preventive maintenance and/or replacing one of three screw conveyor units located in the influent pump screw building. The city has submitted a request for acceptance of the Alternate Measures under Occupational Health and Safety Regulation 9.22.

The employer states that isolation of the confined space using measures specified in Occupational health and safety Regulation 9.18 is not practicable due to the original design of the facility. The alternative measures has been developed because flow in the channel cannot be redirected. The joint and health and safety committee has been consulted with respect to the alternative measures.

The employer has submitted the following documents to WorkSafeBC:

- 1. A request for alternative measures under OHS Regulation 9.22.
- 2. Engineering certification related to isolation gates.
- 3. Email addressing main elements of the submission.
- 4. The process of handling and installing Landy screw.
- 5. Confined space entry procedures and rescue plan.
- 6. Lockout procedure.
- 7. Confined space emergency procedure.

See the documents received in the attachment section related to the request.

The request was reviewed by Deepak Chadda (OHO) in accordance with the guideline OHS Regulation 9.22. The City of Penticton request for acceptance for alternative measures is granted for no more than 2 year from issuance of this inspection report. It is applicable only for workers entering lower screw pump sump area to conduct preventive maintenance and replacing one of the existing screw pump unit.

The decision to accept these alternative measures focuses on the issue of alternate measures for isolation of the confined space under section 9.22 of the OHS Regulation. The decision does not address compliance with other provisions of the Regulation and must not be taken as an endorsement of the overall confined space program for the site.

WorkSafeBC may reconsider the granting of the acceptance, or its terms, if it is later found to have been granted in error, new information is received, or the applicable OHS Regulation provisions are amended.

The employer must post a copy of the inspection report at the work site as required by the OHS Regulation.

WorkSafeBC has a wide range of health and safety information. For general questions regarding workplace health and safety, call toll free within BC 1-888-621-SAFE(7233). For more information, visit www.worksafebc.com

If you have any questions related to this inspection report, please contact:

Deepak Chadda, Occupational Hygiene Officer WorkSafeBC 110 - 2045 Enterprise Way Kelowna, BC V1Y 9T5

Office (250) 717-4313



INSPECTION REPORT
Worker and Employer Services Division
201811321045A

6951 Westminster Highway, Richmond, BC Mailing Address: PO Box 5350, Vancouver BC, V6B 5L5 Telephone 604 276-3100 Toll Free 1-888-621-7233 Fax 604 276-3247

Fax (250) 717-4380 Email deepak.chadda@worksafebc.com

Application for acceptance

The employer has requested that WorkSafeBC accept alternate measures under section 9.22 of the Occupational Health and Safety Regulation. The employer has provided the following documents to support its request:

- 1. A request for alternative measures under OHS Regulation 9.22.
- 2. Engineering certification related to isolation gates.
- 3. Email addressing main elements of the submission.
- 4. The process of handling and installing Landy screw.
- 5. Confined space entry procedures and rescue plan.
- 6. Lockout procedure.
- 7. Confined space emergency procedure.
- 8. HIRA worksheet as a part of hazard assessment.

Employer is planning to conduct preventive maintenance and/or replacing one of three screw pump units located in influent pump screw building.

In accordance with OHS Guideline G9.22-2, a Prevention Officer may make the decision on behalf of WorkSafeBC in this case.

Decision

The acceptance is granted to the employer, City of Penticton, Firm No. 2074, who has responsibility to ensure that the terms of this acceptance are complied with. The acceptance is only applicable to the worksite at 459 Waterloo Avenue. If the location of the worksite changes or if the acceptance granted to one jobsite is to be applied to another jobsite, the employer must apply for another acceptance.

Special terms

The conditions and procedures set out in the above-noted documents must be complied with as well as the following:

- -The employer ensures compliance with other provisions of the OHS Regulation, such as requirements for lockout, addressing slipping and tripping hazards, electrical hazards, rescue planning, worker training, etc
- WCAct 115(2)(e): An employer must provide to the workers the information, instruction, training and supervision necessary to ensure the health and safety of those workers in carrying their work and to ensure the health and safety of other workers at the workplace.
- OH&S Reg 9.22: A measure specified in section 9.18 to control or isolate harmful substances contained in adjacent piping from a confined space is not practicable, and the employer implements alternative measures of control or isolation that are acceptable to the Board
- Clean, respirable air is shown during pre-entry testing and continuous atmosphere monitoring. The facility must immediately



INSPECTION REPORT Worker and Employer Services Division 201811321045A

6951 Westminster Highway, Richmond, BC Mailing Address: PO Box 5350, Vancouver BC, V6B 5L5 Telephone 604 276-3100 Toll Free 1-888-621-7233 Fax 604 276-3247

notify WorkSafeBC and conduct an investigation if clean, respirable air is not shown during pre-entry testing and monitoring.

- Engineered gates are inspected prior to each use and following the requirements of a professional engineer. Ensure that gates are capable of tolerating stress imposed on them.
- Rescue Plan, which includes the practice exercise.
- Fixed Time for daily work permit.
- Follow already developed written confined space entry program

Posting

A copy of these terms, along with any documents to which they refer, must be maintained at the worksite and be available for inspection by WorkSafeBC officers. The same documents must be posted on a suitable bulletin board in legible condition for the period of the acceptance. If affected workers will not receive notice by posting on a bulletin board, then the acceptance must be otherwise made known to all affected workers.

Joint committee

A copy of these terms, along with any documents to which they refer, must be given to the Joint Occupational Health and Safety Committee or to the Worker Health and Safety Representative, as applicable.

Time-limited

The acceptance will be valid for the duration of the project, but for no longer than 2 years from the date of this acceptance.

Verification

The worksite may be inspected by WorkSafeBC officers to confirm these terms are being met.

Failure to comply

If the terms and conditions of this acceptance are not complied with, the acceptance may be deemed to be void. Any non-compliance with the terms and conditions of this acceptance, or other infractions relating to the subject matter of the acceptance, may result in imposition of orders and administrative penalties.

Validity

The granting of this acceptance is based on the completeness and accuracy of the information provided to WorkSafeBC. Any failure to have provided complete and accurate information may result in revocation of the acceptance and imposition of orders and administrative penalties.

Reconsideration

WorkSafeBC may reconsider the granting of the acceptance, or its terms, if it is later found to have been granted in error, new information is received since it was granted or the applicable Occupational Health and Safety Regulation provisions are substantively amended.



6951 Westminster Highway, Richmond, BC Mailing Address: PO Box 5350, Vancouver BC, V6B 5L5 Telephone 604 276-3100 Toll Free 1-888-621-7233 Fax 604 276-3247

REFERENCES

In addition to any orders, or other items, and the information provided in the Inspection Notes section in this Inspection Report, the officer may discuss other health and safety issues with the employer arising out of the inspection. The information below sets out the health and safety requirements discussed with the employer, and unless otherwise noted, violations of these requirements were not observed.

Reference	Details Discussed
OHS9.22(1)	Alternative measures of controls for entering into influent pump
Section 9.18 does not apply if	screw building for preventive maintenance and replacing of screw conveyor was developed and submitted for review which
(a) a measure specified in section 9.18 to control or isolate harmful substances contained in adjacent piping from a confined space is not practicable, and	is located in waste water treatment plant.
(b) the employer implements alternative measures of control or isolation that are acceptable to the Board.	



6951 Westminster Highway, Richmond, BC
Mailing Address: PO Box 5350, Vancouver BC, V6B 5L5
Telephone 604 276-3100 Toll Free 1-888-621-7233 Fax 604 276-3247

Employer #	Mailing Address	Classification Unit #	Operating Location
2074	171 MAIN ST PENTICTON BC V2A 5A9	753004	006

Lab Samples Taken	Direct Readings	Results Presented	Sampling Inspection(s)
N	N	N	

Workers onsite during	Notice of Project
Inspection	Number
10	

Inspection Report Delivered To	Employer Representative Present During Inspection	Worker Representative Present During Inspection	Labour Organization & Local
Randy Craig	Randy Craig	Gord Austrom	

WorkSafeBC Officer Conducting Inspection
Deepak Chadda

*Inspection Time	*Travel Time
13.00 hrs	1.00 hrs

^{*}The time recorded above reflects the inspection time and travel time associated with this inspection report and includes time spent on pre and post-inspection activities. Additional time may be added for subsequent activity.

Right to Review

Any employer, worker, owner, supplier, union, or a member of a deceased worker's family directly affected may, within 45 calendar days of the delivery date of this report, in writing, request the Review Division of WorkSafeBC to conduct a review of an order, or the non-issuance of an order, by contacting the Review Division. Employers requiring assistance may contact the Employers' Advisers at 1-800-925-2233.

WorkSafeBC values your feedback. To obtain that feedback, an external market research provider may be contacting you to complete a survey.